



**CITROEN**



024.999.07


**C5 I** DPF  
**2.0 HDi Turbo Diesel**  
  
**Hatchback, Stationwagon**  
**10/06-08**  
 1997 cc, 138 HP, 101 KW  
 M° DW10BTED4  
 ↳ Ch.nr. NR.PR.10901  
 T° RCRHRG, RCRHRJ, RERHRG, RERHRJ  
 (a) DPS (Capteur de pression différentiel)  
 (b) CORD  
 (c) Echange rénovation, sans nécessaire de montage



024.014.86

**C5 II** DPF  
**2.0 HDi Turbo Diesel**  
  
**Sedan, Stationwagon**  
**02/08-**  
 1997 cc, 138 HP, 101 KW  
 M° DW10BTED4  
 1997 cc, 140 HP, 103 KW  
 M° DW10BTED4  
 T° RDRHF, RDRHR, RWRHF, RWRHR  
 (a) DPS (Capteur de pression différentiel)  
 (b) CORD  
 (c) Echange rénovation, sans nécessaire de montage

**PEUGEOT**



062.999.31

**407** DPF  
**2.0 HDi Turbo Diesel**  
  
**Sedan, Stationwagon**  
**04/04-11/04**  
 1997 cc, 126 HP, 93 KW  
 M° DW10BTED4  
 1997 cc, 136 HP, 100 KW  
 M° DW10BTED4  
 ↳ Ch.nr. NR.PR.10247  
 T° 6DRHLH, 6DRHRE, 6DRHRH, 6ERHLH, 6ERHRE, 6ERHRH  
 (a) DPS (Capteur de pression différentiel)  
 (b) CORD  
 (c) Echange rénovation, sans nécessaire de montage

**407** DPF  
**2.0 HDi Turbo Diesel**  
  
**Sedan, Stationwagon**  
**12/04-01/05**  
 1997 cc, 126 HP, 93 KW  
 M° DW10BTED4  
 1997 cc, 136 HP, 100 KW  
 M° DW10BTED4  
 ↳ Ch.nr. NR.PR.10248  
 ↳ Ch.nr. NR.PR.10310  
 T° 6DRHCH, 6DRHLH, 6DRHRE, 6DRHRH, 6ERHCH, 6ERHLH, 6ERHRE, 6ERHRH  
 (a) DPS (Capteur de pression différentiel)  
 (b) CORD  
 (c) Echange rénovation, sans nécessaire de montage

<p>1706.N1 <b>090-506</b></p> <p>174013 <b>095-014(c)</b> 1731AJ <b>097-219(b)</b> 98-05858480 <b>850-017</b></p> <p>094-500</p> <p>1730.52 <b>190-085</b></p> <p>093-839</p> <p>258-610 258-115 258-036 254-930</p> <p>255-542 254-930 255-190X2 255-169 250-258 255-169</p> <p>000-098(a)</p> <p><b>090-508</b> 1731.RX</p> <p>062.999.32</p>	<p>nécessaire de montage</p>
---	------------------------------

**PEUGEOT**

<p>1706.N1 <b>090-506(a)</b> 1731.RX <b>090-508(a)</b> 174034 <b>095-023(e)</b> 1731AJ <b>097-219(d)</b> 98-05858480 <b>850-017</b></p> <p>094-500</p> <p>1730.52 <b>190-085</b></p> <p>093-839</p> <p>258-610 258-115 258-036 254-930</p> <p>255-542 254-930 255-190X2 255-169 250-258 255-169</p> <p>000-098(c)</p> <p><b>090-542(b)</b> <b>090-543(b)</b> 1706.J5 1731.PV</p> <p>062.999.33</p>	<p><b>407</b> <b>2.0 HDi Turbo Diesel</b> <b>DPF</b></p> <p></p> <p><b>Sedan, Stationwagon</b> <b>02/05-09/07</b> 1997 cc, 126 HP, 93 KW M° DW10BTED4 1997 cc, 136 HP, 100 KW M° DW10BTED4 ↳ Ch.nr. NR.PR.10311 ↳ Ch.nr.NR.PR.11283 T° 6DRHCH, 6DRHLH, 6DRHRE, 6DRHRH, 6ERHCH, 6ERHLH, 6ERHRE, 6ERHRH (a) -&gt; I 10/06, -&gt; INR.PR.10900 (b) I-&gt; 10/06, I-&gt; PR.NR.10900 (c) DPS (Capteur de pression différentiel) (d) CORD (e) Echange rénovation, sans nécessaire de montage</p>
--	--

<p>1706.Q8 <b>CAT N/A</b> 174034 <b>095-023(e)</b> 1731AJ <b>097-219(c)</b> 98-05858480 <b>850-017</b></p> <p>094-500</p> <p>1730.X5 <b>190-193(a)</b></p> <p>092-040</p> <p>255-169 250-260 255-169 255-169 250-258 255-169</p> <p>093-839 <b>190-085</b> 1730.52</p> <p><b>090-543</b> 1731.PV</p> <p>062.014.06</p> <p>000-098(d)</p>	<p><b>407</b> <b>2.0 HDi Turbo Diesel</b> <b>DPF</b></p> <p></p> <p><b>Sedan, Stationwagon</b> <b>10/07-07/10</b> 1997 cc, 138 HP, 101 KW M° DW10BTED4 ↳ Ch.nr. NR.PR.11284 T° 6DRHRE, 6DRHRH, 6ERHRE, 6ERHRH (a) Double tailpipe (b) Single tailpipe (c) CORD (d) DPS (Capteur de pression différentiel) (e) Echange rénovation, sans nécessaire de montage</p>
--	---

<p>1706.Q8 <b>CAT N/A</b> 174034 <b>095-023(e)</b> 1731AJ <b>097-219(c)</b> 98-05858480 <b>850-017</b></p> <p>094-500</p> <p>1730.X5 <b>190-193(a)</b></p> <p>092-040</p> <p>255-169 250-260 255-169 255-169 250-258 255-169</p> <p>093-839 <b>190-085</b> 1730.52</p> <p><b>090-543</b> 1731.PV</p> <p>062.014.06</p> <p>000-098(d)</p>	<p><b>407</b> <b>2.0 HDi Turbo Diesel</b> <b>DPF</b></p> <p></p> <p><b>Sedan, Stationwagon</b> <b>07/10-11</b> 1997 cc, 140 HP, 103 KW M° DW10TED4 ↳ Ch.nr. NR.PR.12292</p>
--	--

