


Vue technique coffre de toit Bermude 100

ART : 2180741



INDEX	CODE 6	DESIGNATION	PHOTO	INDEX	CODE 6	DESIGNATION	PHOTO
1	318045	CHARNIERE		2	281474	CROCHET	
3	285528	FIXATION SUP. VERIN		4	281421	FIXATION INF. VERIN	
5	318046	FIXATION CHARNIERE		6	241632	VERIN COMPAS	
7	769360	BARRE SERRURE CENTRALISEE		8	890895	CONTOUR DE BARILLET	
9	769363	BARILLET		10	810036	RIVET	
11	346799	MOLETTE MASTERFIT		12	346800	JOINT MOLETTE MASTERFIT	
13	CLES	Demande de reproduction de clés sur le portail NEXT					